
MARION COUNTY SURVEYOR'S OFFICE

DEBRA S. JENKINS MARION COUNTY SURVEYOR

SEC. 11 TWN. 15_{N} RNG. 4_{E}

SECTION CORNER RECORD

BRYAN F. CATLIN, PLS TECHNICAL SUPERVISOR



1820 John Hendricks set a corner post with witnesses: Iynn 24" dia. S 25 W 6 links, beech 5" dia. N 25 E 21 links. 2-28 & 29-1860 D.B. Hasbrook found the original corner post and witnesses. Mid 1960's MCSO called a RR spike. 5-2-75 MCSO pulled ties. 11-29-78 Bruer called a cut "X" in concrete 0.24'N of a brass plug previously set in the wrong position. 8-11-88 Greene called a cut "X" in concrete, and referenced the brass plug. 10-19-94 Kiste called a cut "X" that falls in the first R of the RR marking. 12-14-98 Wilcoxen called a cut "X" that falls in the first R of the RR marking, referenced brass plug. 6-17-2003 Wilcoxen called corner a cut "X" in concrete that falls in the first R of the RR marking, referenced brass plug. 10-27-09 Wilcoxen cut a new "X".

REF.	DISTANCE	DESCRIPTION
1.	57.53'	Cut 'x' SE bolt of aluminum pole base
2.	82.52'	Small PK nail S PwP #243-576 A 15" up
3.	49.46'	Mag nail w/brass washer W PwP #52-576 A 8" up
4.	84.89'	Cut 'x' NW bolt of railroad crossing signal
5.	49.29'	Cut 'x' SW bolt of aluminum pole base